

Metrolinx/GO Transit GO Transit Milton Bus Maintenance Facility

Address (Map): 780 Main Street East, Milton, Ontario L9T3P6 Canada

Sector: Transportation

MCW Office: Toronto

Status: Complete



Mechanical:

MCW Consultants Ltd.

Electrical:

MCW Consultants Ltd.

Project Description

This project was a Design Build Proposal. This bus maintenance facility includes administrative offices, drivers and staff facilities, an indoor bus storage and a service area with a bus wash and fuel dispensing facility. The project has attained LEED Silver Certification. This bus maintenance facility includes the construction of administrative offices, drivers and staff facilities, an indoor bus storage and service area with a bus wash and fuel facility.